

## CO<sub>2</sub> meter



- Continuous air quality monitoring
- Data recording
- Also displays temperature and humidity level

In order to continuously monitor, the measurement and display is done continuously on our device, using NDIR sensors. Complies with the ERP air quality decree. LCD display with large colour figures. Data recording and storage on PC. Also displays temperature and humidity.

Adjustable audible alarm. Discreet model to be placed 11 x 11 x 6 cm. Weight 210 gr.

Rechargeable lithium battery (USB cable and adapter included).



- 817063

Date d'impression: 22/11/2024